



Report on aircraft serious incident

Case no: **M-00513/AIG-04**

Date: **26. February 2013**

Location: **Keflavik Airport (BIKF)**

Description: **Uncommanded left roll during final approach**

Investigation per Icelandic Law on Transportation Accident Investigation, No. 18/2013 shall solely be used to determine the cause(s) and contributing factor(s) for transportation accidents and incidents, but not determine or divide blame or responsibility, to prevent further occurrences of similar cause(s). This report shall not be used as evidence in court and it shall not be used to determine or divide blame or responsibility.

Contents

Contents	2
Synopsis	3
1 Factual information	4
1.1 History of the flight	5
1.2 Injuries to persons	12
1.3 Damage to aircraft	12
1.4 Other damages	12
1.5 Personnel information	13
1.6 Aircraft Information	13
1.7 Meteorological information.....	14
1.8 Aids to navigation	14
1.9 Communications	14
1.10 Aerodrome information	14
1.11 Flight Recorders	14
1.12 Wreckage and Impact information.....	15
1.13 Medical and pathological information	15
1.14 Fire.....	15
1.15 Survival aspects.....	15
1.16 Test and research.....	15
1.16.1 Moog inspection of spoiler actuators	18
1.17 Organizational and management information.....	21
1.18 Additional information	21
1.19 Useful or effective investigation technique	22
2 Analysis	24
2.1 Flight operation	24
2.2 Operational procedures	27
2.3 Air traffic control.....	27
2.4 Communication	28
2.5 Aircraft maintenance.....	28
2.6 Aircraft systems	28
2.7 Actions already taken as a result of this incident.....	29
3 Conclusion	30
3.1 Findings	30
3.2 Causes.....	32
4 Safety Recommendations	33

Synopsis

Icelandair B757-200, TF-FIJ, was enroute to Keflavik Airport (BIKF), on a flight from Copenhagen Airport (EKCH). At top of descent, the airplane's right hydraulic system failed when a hydraulic tube in the wheel well cracked. The flight crew performed the necessary actions to prepare for landing with inoperative systems as a result of the right hydraulic system failure.

At 22:26, during night, on a 7 NM final approach to RWY 20 at Keflavik Airport, when the flaps had been fully deployed the airplane suddenly rolled to the left. The airplane's center autopilot was engaged. The roll was uncommanded and caused partial loss of control. When the flight crew was trying to regain full control of the airplane, flap overspeed occurred. Following the flap overspeed the airplane was pitched down. The airplane's speed continued to increase and the airplane started to descend rapidly. This resulted in the flight crew declaring an emergency. The investigation revealed that the flight crew had regained full control of the airplane 2 minutes and 42 seconds after the uncommanded left roll. Three minutes and 22 seconds after the left roll and partial loss of control, the flight crew contacted ATC¹ and advised that they had regained full control of the airplane and were ready to commence another approach to the airport. At that time the airplane was located south of Straumsvík, near Hafnarfjörður.

The investigation of the data from the FDR revealed that there had been a latent spoiler module failure present for the past 27 flights. Inspection of the spoiler system revealed a latent failure in the actuator of spoiler #6, due to cracked Blocking and Thermal Relief Valve Housing.

Full deployment of the flaps, with the right hydraulic system unpressurized and the Blocking and Thermal Relief Valve Housing cracked, caused spoiler #6 to float. This caused in asymmetrical lift between the left and the right wings, resulting in a rolling moment to the left.

Several safety recommendations are issued.

¹ Air Traffic Control

1 Factual information

Factual information	
Place:	On final approach for RWY 20 at Keflavik Airport (BIKF), 7 NM from the runway at an altitude of 2400 feet
Date:	February 26 th , 2013
Time²:	22:26:47
Aircraft:	• type: Boeing 757-200 • registration: TF-FIJ • year of manufacture: 1991 • serial number: 25085 • CoA: Valid • Nationality: Icelandic
Type of flight:	Scheduled commercial flight
Persons on board:	6 crew members 165 passengers
Injuries:	None
Damage:	None
Short description:	The airplane rolled uncommanded to the left, while on final approach
Owner:	Airco ehf
Operator:	Icelandair
Meteorological conditions:	Visual Meteorological Conditions (VMC)
Flight rules:	Instrument Flight Rules (IFR)

² All times in the report are UTC and where applicable local times are shown in ().

1.1 History of the flight

On the evening of February 26th 2013 Icelandair B757-200 airplane, TF-FIJ, was enroute to Keflavik Airport (BIKF), on a flight from Copenhagen Airport (EKCH). The first officer was the pilot flying, as the commander had flown the previous flight leg from Keflavik to Copenhagen. The airplane's center autopilot was engaged.

Shortly before top of descent, at 21:45 when at FL360, the fourth cabin attendant³, located in back of the airplane, called the flight crew on the intercom system. He reported that, about 5 minutes earlier, he started noticing, in the center area of the airplane, a constant, steady bass like sound unlike anything he had heard before in flight. The first officer scanned the instruments and did not observe any indication of a problem. He advised that there were no abnormalities on the flight crew's instruments and asked the flight attendant if he could distinguish from which side of the airplane this unusual sound was emanating from. The cabin attendant replied that he could not locate the source of the sound, it was all over he stated, but most noticeable in the wing area and aft of that location. The flight crew discussed what the source of this abnormal sound in the cabin could be, as there was no abnormal indication on the flight deck displays. Shortly thereafter the senior cabin attendant entered the flight deck and reported that she went to the aft cabin and also noticed the unusual sound the fourth cabin attendant had previously reported.

At 21:52, when the flight crew was communicating with an ATC officer and about to initiate descent⁴, the flight crew noticed the floor vibrating and the following indication appeared on the EICAS monitor:

- R HYD QTY

There was a problem with the right hydraulic quantity, so the flight crew consulted the QRH⁵. While they were consulting the QRH, a second EICAS message appeared:

³ The cabin attendants have a ranking of: Senior-, second-, third- and fourth cabin attendant

⁴ Top of descent

⁵ Quick Reference Handbook

- R HYD SYS PRESS

The flight crew realized that they had lost the right hydraulic system and started working the “Hydraulic Quantity” and the “Hydraulic System Pressure (R only)” checklists from the QRH⁶.

The flight crew was aware that due to the RH hydraulic system failure, some spoilers on each wing would be inoperative. They also discussed that according to the QRH, because of the loss of the RH hydraulic system, the right autopilot, right thrust reverser, the right stabilizer trim and the auto brake system would also not be functioning. Finally they also discussed that this would affect the landing distance, due to non-normal landing configuration, but because of the length of the RWY at BIKF that would not be a factor. During descent the flight crew tested the spoilers and found them to be performing poorly and the following indication showed up on the EICAS monitor:

- SPOILERS

The flight crew requested from ATC a vector to RWY 20 and to be established early on the localizer. Until on final approach, the airplane was in IMC⁷. The localizer was intercepted, at 2600 feet altitude about 7.8 NM from the runway.

The flaps were extended and the landing gear selected down. At 22:26:47, during night, when the flaps had reached the 30° position, the flying pilot [first officer] noticed vibration and the airplane started an uncommanded roll to the left. The airplane was at an altitude of 2400 feet and a distance of 7 NM from the runway when this occurred. The flying pilot scanned the instruments, expecting to see asymmetry indications on the EICAS, but there were none. The flying pilot then noticed that according to the “trend vector” the airplane was beginning to turn to the left. See Figure 1 for details.

⁶ Quick Reference Handbook, pages 13.2 and 13.10-13.11

⁷ Instrument Meteorological Conditions




Figure 1: The airplane (ICE213) starts to turn to the left (ATC radar)

According to the pilot flying, he had not managed to set the go-around altitude at 3000 feet as required by SOP⁸ when the upset occurred.

The flying pilot disengaged the autopilot and tried to correct the airplane's heading by steering full right. Initially there was no response to the pilot's right turn steering wheel input. No additional warning was indicated on the EICAS.

Five seconds after the upset⁹, the commander commanded a go-around. The airplane continued its uncommanded left roll and reached its maximum left bank angle of 34°, 8 seconds after the upset. The commander started to retract the flaps. As the flaps started to retract from the 30° to the 20° position, about 20 seconds after the initial upset, the airplane bank angle decreased to 18°. When the flaps were somewhere between 20° and 5° the pilot felt the airplane responding to the right steering wheel input.

⁸ Standard Operating Procedures

⁹ To distinguish between the right hydraulic failure at top of descent and the uncommanded turn on the final approach, the start of the uncommanded turn is called upset in the report

The Keflavik tower ATC officer contacted the flight crew 26 seconds after the initial upset and requested a confirmation of continuation of the approach. The flight crew replied that they were going around.

The airplane started to climb in its go-around mode and levelled off at 4000 feet 50 seconds after the upset. One minute after the upset the airplane was wings level, on heading 135° and the computed airspeed was at 200 knots and increasing. About six seconds later, when the flaps were still being retracted and the flaps were in the 5° position the airplane exceeded the flap speed limit of 220 knots.

Following the flap overspeed the airplane was pitched down to descend down to go-around altitude. The airplane's speed continued to increase and the airplane started to descend rapidly. The pilot flying was aware of high descent rate developing, but did not immediately take the proper action to correct it. According to the pilots they began to question and discuss their instruments at this time, as the possible cause of the uncommanded roll.

One minute and 21 seconds after the upset, at 22:28:09, following a descent rate of about 3500 feet/min for few seconds and the pilot flying declaring that they were descending too quickly, the commander declared an emergency to ATC. At the same time flap retraction was stopped with the flaps in 1° flap position, leaving the airplane in a flap overspeed condition. At this time the airplane was located as shown in Figure 2.




Figure 2: Location of TF-FIJ when the commander declared an emergency at 22:28:09

The ATC officer in the Keflavik tower asked if they could reach the airport. The commander answered “*NEGATIVE, we have problem with the controls... just a moment we are trying to regain control*”. Following this, the ATC officer initiated the airport’s emergency response plan.

One minute and 52 seconds after the upset, the airplane levelled off at 3000 feet altitude.

Two minutes and 17 seconds after the upset, the Keflavik tower ATC officer contacted the flight crew advising that they were located slightly north of short final for RWY 29, which was now set up for them.

The commander took over as the pilot flying two minutes and 22 seconds after the upset, and seven second later the first officer replied to the ATC officer [in Icelandic]: “*We’re going to start by regaining control of the airplane. We have lost the right hydraulic system and it behaves strangely. We are trying to regain control and would like to continue the present course if possible.*” At this time the airplane was located as shown in Figure 3.




Figure 3: The flight crew replied to Keflavik tower ATC officer that they were trying to regain control

The ATC officer advised [in Icelandic] that they could maintain the present course, but requested that the flight crew climb before reaching higher ground. At this time the airplane was crossing the coastline in “Hvassahraun” south of “Hafnarfjörður”, heading towards “Bláfjöll”, at an altitude of 3500 feet and already gaining altitude.

The investigation revealed that the flight crew had regained full control of the airplane 2 minutes and 42 seconds after the uncommanded left roll, when the flap overspeed condition was stopped.

Three minutes and 22 seconds after the initial upset, the flight crew contacted ATC and advised that they had regained control of the airplane. At this time the airplane was located south of “Straumsvík” as shown in Figure 4.




Figure 4: The flight crew contacted ATC and notified that they had regained control at 22:30:09

In Figure 5 below, the flight radar track is shown with combined details on what occurred during the incident.




Figure 5: Detailed explanation on radar plot

The flight crew returned for approach to RWY 20 at Keflavik airport. During the maneuvering of the airplane back to the final approach position they discussed the upset and concluded that it had to do with the flight controls and that it occurred when the flaps were fully deployed. The flight crew therefore decided to perform the second landing using a long approach and only 15° flap positioning.

The flight crew requested, and the airline dispatched, a trauma team to meet the passengers after the landing. The second landing attempt was uneventful and the airplane landed on RWY 20 at 22:45:33. After the landing, the commander informed the passengers that during the final approach they'd had problems with the flight controls of the aircraft and discontinued approach and then returned for landing.

1.2 Injuries to persons

None.

1.3 Damage to aircraft

None.

1.4 Other damages

None.

1.5 Personnel information

Commander										
Age:	49 years old									
License:	ATPL/A									
Medical certificate:	Class 1									
Ratings:	B757/B767 – IR									
Experience:	<table><tbody><tr><td>Total all types:</td><td>12660</td></tr><tr><td>Total on type:</td><td>7134</td></tr><tr><td>Last 90 days:</td><td>145</td></tr><tr><td>Last 24 hours:</td><td>3</td></tr></tbody></table>		Total all types:	12660	Total on type:	7134	Last 90 days:	145	Last 24 hours:	3
Total all types:	12660									
Total on type:	7134									
Last 90 days:	145									
Last 24 hours:	3									
Previous rest period:	Well rested									

First Officer										
Age:	34 years old									
License:	ATPL/A									
Medical certificate:	Class 1									
Ratings:	B757/B767 – IR									
Experience:	<table><tbody><tr><td>Total all types:</td><td>3347.8 hours</td></tr><tr><td>Total on type:</td><td>2770.2 hours</td></tr><tr><td>Last 90 days:</td><td>104.3 hours</td></tr><tr><td>Last 24 hours:</td><td>6.6 hours</td></tr></tbody></table>		Total all types:	3347.8 hours	Total on type:	2770.2 hours	Last 90 days:	104.3 hours	Last 24 hours:	6.6 hours
Total all types:	3347.8 hours									
Total on type:	2770.2 hours									
Last 90 days:	104.3 hours									
Last 24 hours:	6.6 hours									
Previous rest period:	Well rested									

1.6 Aircraft Information

On the previous flight leg (Keflavik to Copenhagen) the airplane had to turn back to Keflavik due to LH EICAS computer failure. As this was MEL¹⁰ A item, it was deferred for 24 hours.

¹⁰ Minimum Equipment List

1.7 Meteorological information

The METAR report for Keflavik Airport between 22:00 and 23:00 on February 26th, 2013 was as follows:

METAR BIKF 262200Z 19024KT 9999 FEW024 BKN038 BKN080 06/03 Q1006
METAR BIKF 262230Z 19029G40KT 9999 -DZ FEW018 BKN038 BKN080 06/03 Q1006
METAR BIKF 262300Z 19025KT 9999 -DZ FEW018 BKN036 BKN060 06/04 Q1006

1.8 Aids to navigation

At the onset of the incident the airplane was on final approach on the ILS for RWY 20 at BIKF. After the incident the flight crew requested and received vectors from ATC back to the approach for RWY 20.

1.9 Communications

During the incident communications between Keflavik tower ATC officer and the flight crew took place on the Keflavik (BIKF) tower frequency 118.3 MHz as well as on Keflavik approach frequency 119.3 MHz's.

Once a go-around had been initiated and reported to Keflavik tower, the air traffic controller asked the flight crew to switch over to Keflavik approach at 119.3 MHz's. The flight crew acknowledged the frequency change command, but stayed on the tower frequency for the remainder of the incident. Once control of the airplane had been regained, and the frequency change command was repeated by the ATC officer 4 minutes and 44 seconds later, while the airplane was flying at an altitude of 7000 feet, the flight crew switched to the approach frequency.

1.10 Aerodrome information

The incident occurred during approach to RWY 20 at Keflavik Airport (BIKF).

1.11 Flight Recorders

The Icelandic Transportation Safety Board¹¹ removed the flight data recorder (FDR P/N 980-6022-001 and S/N 3464) and the cockpit voice recorder (CVR P/N 980-4700-042 and S/N 6389) from the airplane. The FDR and the CVR were

¹¹ ITSB, or „Rannsóknarnefnd samgönguslysa“ (RNSA) in Icelandic

transported to the UK Air Accident Investigation Branch, where data was downloaded and analyzed.

During the analysis of the FDR, it was discovered that spoiler module failure [SPOILER MODULE0534] had been present during the airplane's previous 27 flights. It was also confirmed that the right hydraulic system failed at top of descent, and that the flaps had been deployed to the full position when the incident occurred.

1.12 Wreckage and Impact information

Not applicable.

1.13 Medical and pathological information

Not applicable.

1.14 Fire

Not applicable.

1.15 Survival aspects

Not applicable.

1.16 Test and research

After the FDR readout, it was known that there had been a spoiler failure present for the past 27 flights. The Icelandic Transportation Safety Board therefore requested the operator to inspect and test the spoiler system on the airplane. The spoiler system on the airplane was subsequently tested, using the following method:

- Removing hydraulic pressure from the spoiler's system
- Physically, trying to move the spoilers by a "strong" hand
- Spoiler #2 did not move
- Spoiler #4 was stiff, but did move
- Spoiler #6 was loose and moved easily
- See Figure 6 for details on spoilers location




Figure 6: Spoilers on B757-200 airplanes

It was confirmed that spoiler #4 and #6 were not fully locking down as required during hydraulic system backpressure loss. It was decided to remove all three spoiler actuators on the left wing that were connected to the right hydraulic system (# 2, #4 and #6) and to send them for further testing at the component manufacturer's site, Moog. Figure 7 shows one of the actuators shipped to Moog.




Figure 7: One of the actuators shipped to Moog

After spoiler #4 and #6 were found not to be fully locking down as required Boeing aerodynamic specialists performed simulated computer tests and compared them to the FDR readout, while the spoiler units were being shipped to Moog. According to Boeing, the 757-200 with winglets desktop simulation was used to evaluate various left wing spoiler float scenarios. The simulation is a six degree of freedom non-linear model that has been updated to match flight data. Various spoiler float deflections were modeled and the resulting control wheel requirement for level flight was evaluated. The right hydraulic system powers spoilers 2, 4, and 6, so these spoilers (mainly 2 and 6) were the focus of the analysis. A flight condition was chosen at flaps 20, shortly before flaps 30 was selected during the event flight, as the airplane was closest to steady state with a clear right control wheel requirement. Past analyses have shown that the estimated float angle for spoiler 2 (outboard flight spoiler) is around 10 degrees, so that deflection was modeled in the simulation. The resulting control wheel required to trim was around 8 degrees to the right, which is consistent with the control wheel requirement in the FDR data. A nominal float angle for spoiler 6 (inboard flight spoiler) was assumed to be 10 degrees as well. Modeling this spoiler deflection resulted in a slightly lower control wheel requirement of around 5 degrees. Modeling a 10-degree float for both spoiler 2 and 6 at the same time resulted in a required control wheel input of approximately 11.5 degrees, which is also close to what was observed prior to the roll upset. While the event airplane was configured at flaps 20, control wheel inputs between 5 and 12 degrees were observed, so it was difficult to identify which scenario was more likely. A flight condition at flaps UP was also evaluated. A spoiler 2 float of 5 degrees and a spoiler 6 float of 10 degrees were modeled and simulated separately. The spoiler 2 float scenario resulted in a control wheel requirement of 5 degrees while the spoiler 6 float scenario required a slightly higher control wheel input (6 degrees). The flaps 20 float scenarios were also modeled in the simulation using rolling moment coefficients obtained from wind tunnel/flight test data. This was conducted as an analysis verification check. The control wheel required to trim was evaluated, and the resulting values were similar to the values determined by deflecting each spoiler panel. It is also important to note that data based on flight test indicate that spoiler float angles significantly increase once the flaps are extended beyond 20 degrees. According to Boeing, the flaps 20 and flaps UP simulation data supported a spoiler float scenario by either spoiler 2 or 6 (a dual spoiler float scenario was deemed unlikely).

1.16.1 Moog inspection of spoiler actuators

Several tests were performed on the spoiler actuators to simulate different failure modes.

	Spoiler #2	Spoiler #4	Spoiler #6
	Data plate missing	P/N 3321500-09A S/N 8950608	P/N 3321480-10A S/N 8926513
Leak test	Passed	Passed	Failed
Two sides pressure test	Passed	Failed	Failed
Hold down test	Passed	Failed	Failed
Hysteresis test	Passed	Passed	Failed
Operation test	Not needed	Passed	Passed

The actuator for spoiler #2 was ruled out as a factor in the incident and teardown inspection was performed on the actuators for spoilers #4 and #6.

The teardown inspection on the actuator for spoiler #4 revealed microscopic scratches on the blocking and thermal relief valve seat (item 90 in Figure 8) and the poppet (item 80 in Figure 8). These microscopic cracks were believed to be the source of the failed tests on the #4 spoiler actuator, as they allowed tiny leak of hydraulic fluid.




Figure 8: Actuator of spoiler #4 - Blocking and thermal relief valve – Scratches on seat and poppet

In the case of the actuator for spoiler #6, once the disassembly started it quickly became apparent that the Blocking and Thermal Relief Valve Housing (item 140 in Figure 9) was fractured. The component manufacturer (Moog) advised having seen this failure mode on several occasions, during overhauls, although never as a part of reported in-flight incident. These cases had not been reported to Boeing (the airplane manufacturer).




Figure 9: Actuator of spoiler #6 - Blocking and thermal relief valve - Housing fractured

According to Boeing the function of the Blocking and Thermal Relief Valve Housing is to hold down the spoiler in the event of a hydraulic failure. Normally, hydraulic pressure would hold the broken halves together, but with the loss of hydraulic pressure, the halves separate, allowing large scale leakage and spoiler float.

1.17 Organizational and management information

Not applicable.

1.18 Additional information

During initial inspection of the airplane, hydraulic tube P/N 271N6444-1237 located in the right wheel well, between the filter housing and an AC hydraulic pump, was found cracked. This hydraulic tube was a part of the right hydraulic system. See Figure 10 for details.



Figure 10: Cracked hydraulic tube

1.19 Useful or effective investigation technique

The NTSB¹² took part in the investigation as the State of manufacture and performed fracture analysis of the fractured Blocking and Thermal Relief Valve Housing (see Figure 11).



Figure 11: Fractured Blocking and Thermal Relief Valve Housing

The analysis showed that the valve housing cracked along the edge of a cylindrical channel that contained six ports (holes) spaced at 60° intervals around the circumference of the valve. Figure 12 shows part of the fracture surface of the Blocking and Thermal Relief Valve Housing under magnification using an optical microscope. On the left and the right side of the picture two of the six shuttle valve ports are shown, marked as “Ports on sidewall” and highlighted in red, and the fracture surface between those ports. The fracture initiated along the outer circumference (white curves arrows) and progressed radially inwards by fatigue up to the yellow-dashed line. At the yellow-dashed line, the orientation of the fracture surface changed to one consistent with an overstress fracture. Similar damages were observed between other ports along the circumference of the thermal relief valve housing.

¹² The National Transportation Safety Board, United States of America




Figure 12: Enlarged view of the thermal relief valve housing fracture surface

2 Analysis

2.1 Flight operation

During cruise, 34 minutes and 3 seconds prior to the uncommanded left roll, the right hydraulic system failed as hydraulic tube P/N 271N6444-1237 cracked. Approximately 3 minutes after this, the autopilot commanded right control wheel (~ 5 degrees) to maintain wings level. The right control wheel requirement reduced as the airplane descended and vane angle of attack increased before returning as the airplane leveled out.

The FDR data show the airplane on descent approaching 10,000 feet pressure altitude with the center autopilot engaged in Flight Level Change (FLCH) and Lateral Navigation (LNAV) mode. The airplane was following its target airspeed and was in the process of descending to a target baro-corrected pressure altitude, which was selected on the Mode Control Panel (MCP), of just below 2500 feet. The autopilot was commanding a slight right control wheel input to maintain wings level.

28 minutes and 20 seconds after the right hydraulic system failed, the speedbrakes were deployed, eventually reaching maximum in-flight detent. At this speedbrake deflection (spoiler panel deflections not recorded), the control wheel input returned to around neutral. Computed airspeed decreased as the crew prepared for flap extension.

28 minutes and 40 seconds after the right hydraulic system failed, there was a discrete change that indicated the failure of spoiler panel pairs 2/11 and 6/7.

With the speedbrakes remaining deployed, the flaps were extended to 1 degree 30 minutes after the right hydraulic system failed.

30 minutes and 20 seconds after the right hydraulic system failed, a failure condition was indicated in spoiler panel pair 4/9. As stated earlier, spoiler deflections are not recorded, but all of the evidence collected at this point indicated a likely spoiler float scenario on the left wing.

As the airplane continued to descend towards its target altitude, the flaps were extended to 5 degrees, a left turn was initiated (autopilot roll mode changed to

Heading Select [HDG SEL] mode), and the speedbrakes were stowed. Once the speedbrake handle was stowed, the autopilot returned to commanding a slight right control wheel input.

32 minutes and 20 seconds after the right hydraulic system failed, just prior to leveling out at the target altitude, the flaps extended to 15 degrees position.

The airplane leveled off at the target altitude as the autopilot pitch mode transitioned to Altitude Capture before engaging in Altitude Hold mode. This was 32 minutes and 36 seconds after the right hydraulic system failed.

Approximately 2 seconds later, the autopilot roll mode transitioned to Localizer mode, and the airplane turned left again to capture the localizer. After rolling out of the left bank, the airplane required a slightly higher average right control wheel input to maintain wings level. After the flaps were extended to 20 degrees, the control wheel requirement increased more to the right.

Glideslope deviation reduced towards zero as the airplane approached the glideslope beam from below while flying straight and level.

At 22:26, during night, on a 7 NM final approach to RWY 20 at Keflavik Airport, after the airplane captured the glide slope, the pilot flying called for flaps 30. The autopilot pitch mode transitioned to Glideslope (G/S) mode just prior to flap extension to 30 degrees.

As the flaps extended from 20 to 30 degrees, the autopilot increased the right control wheel input until reaching its maximum control wheel authority (22 degrees). The airplane initially rolled slightly left, but once the autopilot ran out of control wheel authority, the airplane rolled rapidly to the left. This occurred at 34 minutes and 3 seconds after the right hydraulic system failed. The autopilot did not disengage.

The pilot flying realized that the airplane was rolling to the left and rapid right control wheel and rudder pedal inputs were commenced by him 8 seconds after the uncommanded left roll. This was when the airplane reached an approximate

30-degree left bank angle. Multiple right control wheel inputs reached approximately 80 degrees.

The autopilot and autothrottle concurrently disengaged as the flight crew commanded the control wheel and rudder pedal inputs.

Following the uncommanded left roll reaching a maximum bank angle of 34°, the flight crew initiated a go-around, which calls for flaps 20 selection according to Icelandair procedures. This was done when the airplane was being flown manually and the go-around altitude had not been set to the required 3000 feet.

The pilot flying increased the engine power, pitched the airplane up and started retracting the flaps. When the flaps were retracted and go around power had been applied the airplane started responding to the pilots commands. The flight crew managed to reduce the bank angle, but did not have the roll under control.

As a result, about 17 seconds after the upset, the flight crew was tackling the uncommanded roll and initiating a go-around at the same time. At this time, the left bank angle had decreased to approximately 10 degrees, and the flap handle was moved to the flaps 20 detent. During this time, the airplane began pitching up, reaching a maximum of close to 20 degrees before the crew commanded nose-down column, resulting in a pitch attitude decrease to around 5 degrees and a normal load factor decrease to 0.3 g's.

About 27 seconds after the upset, the bank angle increased to approximately 16 degrees to the left before the airplane rapidly rolled to the right around the same time that the flaps retracted to 20 degrees. The airplane likely rolled to the right because the flight crew was still maintaining a right control wheel and rudder input. The airplane reached an approximate 10-degree right bank angle before the flight crew arrested the roll rate to the right with a left control wheel input. Around the same time, the autothrottle was re-engaged, and the autopilot Pitch mode transitioned from G/S mode to Go-Around (G/A) Pitch mode and the autopilot Roll mode transitioned from Localizer mode to G/A Roll mode, although the autopilot was not re-engaged.

About 40 seconds after the upset, the airplane overshot its go-around altitude of 3000 feet while the flight crew was still tackling the uncommanded roll.

The airplane pitched to approximately 20 degrees before the pitch attitude decreased to around zero degrees, on average. The autopilot modes continued to change, transitioning from G/A mode to Altitude Capture (ALT CAP) mode and eventually Altitude Hold (ALT HOLD) mode while the autopilot Roll mode transitioned to HDG SEL mode. In this case, with the autopilot not engaged, these modes were providing Flight Director (FD) guidance.

Flap overspeed occurred at 62 seconds after the upset, as the flaps were retracting slowly while the airplane speed was increasing rapidly.

The airplane speed continued increasing under flap overspeed condition, while at the same time the airplane started to descend with a high rate of descent of up to 3500 feet per minute, for less than 5 seconds, and the pilot flying declaring that they were descending too rapidly. It was after this escalation of the incident that the commander declared emergency, one minute and 21 seconds after the upset.

The first officer was the pilot flying when the incident occurred and the commander took over as the pilot flying 2 minutes and 21 seconds after the upset (the uncommanded roll).

The flaps were left in the flap 1 position, leaving the airplane in a flap overspeed condition for 1 minute and 40 seconds. According to the pilots they were overloaded with the task at hand and forgot the flaps.

2.2 Operational procedures

When the airplane right hydraulic system failure occurred at top of descent the flight crew worked the “Hydraulic Quantity” and the “Hydraulic System Pressure (R only)” checklists in the QRH. The flight crew was therefore well aware prior to approach, which systems would not be working due to the non-functioning right hydraulic system.

2.3 Air traffic control

ATC at Keflavik airport, both the tower and the approach, assisted the flight crew:

- ATCO¹³ at Keflavik tower set up RWY 29 for short final and offered it to the flight crew as an alternate after the upset
- ATCO at Keflavik tower initiated the airport's emergency response plan
- ATCO at Keflavik approach provided the flight crew with vectors back to RWY 20, reducing their work load

2.4 Communication

The flight crew stayed on tower frequency despite having received and acknowledged frequency change instructions. The investigations determined this to have occurred due to high workload of the flight crew during the incident.

2.5 Aircraft maintenance

The fractured Blocking and Thermal Relief Valve Housing, in spoiler #6 actuator, was a latent¹⁴ failure. It did not raise any flags with maintenance, because with the right hydraulic system working the hydraulic pressure in the actuator kept the spoilers from floating.

Once the right hydraulic system became non-functioning, due to the cracked hydraulic tube, the hydraulic back pressure in the actuator was no longer present. This, combined with the fractured Blocking and Thermal Relief Valve Housing, allowed spoiler #6 to float when the flaps were fully extended.

2.6 Aircraft systems

The crack to the hydraulic tube, P/N 271N6444-1237, located in the right wheel well, caused the loss of the right hydraulic system at top of descent. The crack is believed to have been caused by weld flaw.

The FDR data shows evidence of a lateral asymmetry consistent with a spoiler panel 6 float scenario beginning shortly after the right hydraulic system failed in cruise. Floating spoiler #6 separated the airflow over a section of the left wing, resulting in a rolling moment to the left.

¹³ Air Traffic Control Officer

¹⁴ Underlying failure not being noticed

2.7 Actions already taken as a result of this incident

After the ITSB opened its investigation into this incident, the following actions have already been performed or initiated:

Icelandair:

- Inspected its B757 fleet for this failure type, using the spoiler physical hand movement inspection method described in chapter 1.16 with the spoiler's hydraulic system unpressurized
- Replaced three actuators on the incident airplane, as part of the incident investigation
- Inspection of the rest of its 757 fleet resulted in replacement of four actuators
- Reviewed the incident in pilot re-current training

Moog:

- Redesigned the Blocking and Thermal Relief Valve Housing with thicker material section and more radius in the area of the fracture surface. The redesigned Blocking and Thermal Relief Valve Housing is made from stainless steel instead of aluminum. This results in better fatigue performance of the Blocking and Thermal Relief Valve Housing

Boeing:

- Issued fleet team bulletin 757-FTS-27-14022 notifying operators of spoiler float condition in association with a hydraulic system pressure loss, resulting in an uncommanded roll of an airplane when the flaps extended between 25° and 30° position
- Advised operators that the issue was related to failed spoiler power control unit (PCU) blocking and thermal relief valve
- Released Flight Crew Operation Manual Bulletin TBC-21, regarding the spoiler float issue and provided flight crews with recommended procedures to follow in the event of uncommanded roll due to floating spoiler in the event of a hydraulic pressure loss
- Plans to release Boeing Alert Service Bulletin 757-SB-27A0154 on June 25 2016 in coordination with Moog component level service bulletin to install new improved fatigue life stainless steel blocking and thermal relief valve into spoiler PCUs

3 Conclusion

3.1 Findings

There had been a spoiler module failure present for the past 27 flights before the incident. This was caused by latent failure in the actuator of spoiler #6, due to a cracked Blocking and Thermal Relief Valve Housing.

When a hydraulic tube in the right wheel well, part of the right hydraulic system cracked, it caused a loss of hydraulic pressure in the right hydraulic system at the top of descent. The crack in the hydraulic tube is believed to have been caused by weld flaw.

The cracked Blocking and Thermal Relief Valve Housing in the actuator of spoiler 6, combined with the loss of hydraulic pressure in the right hydraulic system, resulted in floating of spoiler panel 6.

The airplane center autopilot was engaged. It is evident from the data that before the uncommanded left roll the autopilot was correcting for a lateral asymmetry that was inducing a left rolling moment. The relatively small amount of autopilot-commanded control wheel offset went unnoticed by the crew, which had the effect of masking the lateral asymmetry until saturation occurred.

The control wheel requirement to maintain wings level increased as the flaps extended. Initially the autopilot was able to sufficiently control the rolling moment due to the floating spoiler panel. Once the flaps were extended to 30 degrees, the autopilot control wheel authority was saturated at 22 degrees, and the autopilot could no longer counter the rolling moment due to the floating spoiler.

This resulted in an uncommanded roll to the left. The autopilot did not disengage.

Following the uncommanded left roll reaching a maximum bank angle of 34°, the flight crew initiated a go-around, which calls for flaps 20 selection according to Icelandair procedures.

Following the uncommanded roll, while the pilots were trying to regain control of the airplane, flap overspeed occurred. Then the airplane was pitched down. This resulted in a high rate of descent of up to 3500 feet per minute, which lasted for

less than 5 seconds. The pilot flying stated that they were descending too rapidly and the commander declared an emergency.

The commander took over as the pilot flying 2 minutes and 21 seconds after the upset (the uncommanded roll).

The investigation revealed that the flight crew had regained full control of the airplane 2 minutes and 42 seconds after the uncommanded left roll, when the flap overspeed condition was stopped.

The uncommanded roll was due to a rolling moment induced by a floating spoiler panel that could not be countered by the autopilot's control wheel authority following the selection of flaps 30.

3.2 Causes

- Latent failure in the actuator of spoiler #6, due to a cracked Blocking and Thermal Relief Valve Housing
- Loss of right hydraulic system pressure due to cracked hydraulic tube
- Full deployment of the flaps, with the right hydraulic system unpressurized and the Blocking and Thermal Relief Valve Housing cracked, caused spoiler #6 to float
- Floating spoiler #6 separating the airflow over a section of the left wing, causing the airplane to roll to the left due to unbalance in lift between the left and the right wings

4 Safety Recommendations

Moog:

- In co-operation with the airplane's manufacturer, set up a program to support fleet wide replacement of the blocking and thermal relief valve housing with the fatigue improved unit made from stainless steel

Boeing:

- Issue the planned service bulletin 757-SB57A0154 to support fleet wide replacement of the Blocking and Thermal Relief Valve Housing in co-operation with the actuator's manufacturer
- Research other Boeing large transport category aircraft for similar spoiler actuator design and take corrective action as needed

FAA:

- Research the need for making inspections, and possible replacement, of spoiler actuator's Blocking and Thermal Relief Valve Housing mandatory via issue of airworthiness directive, for Boeing 757 airplanes
- Research the need for making inspections, and possible replacement, of spoiler actuator's Blocking and Thermal Relief Valve Housing mandatory via issue of airworthiness directive, for other large transport category aircraft with similar spoiler actuator design

The following board members approved the report:

- *Bryndís Lára Torfadóttir, board member*
- *Gestur Gunnarsson, board member*
- *Hörður Arilíusson, deputy board member*

Reykjavik, 13. August 2015

*On behalf of the Icelandic Transportation Safety Board
Ragnar Guðmundsson, Investigator-In-Charge*