

KÖZLEKEDÉSBIZTONSÁGI SZERVEZET

TRANSPORTATION SAFETY BUREAU

FINAL REPORT

2007-307-4 Serious incident

> Budapest 14 July 2007

Boeing-747-236SF TF-ATX

The sole objective of the technical investigation is to reveal the causes and circumstances of aviation accidents, incidents or irregularities and to initiate the necessary technical measures and make recommendations in order to prevent similar cases in the future. It is not the purpose of this activity to apportion blame or liability.

This present investigation was carried out on the basis of

- Act XCVII of 1995 on aviation,
- Annex 13 to ICAO Convention on Civil Aviation, put in force in Hungary by MTCW (Ministry of Transport, Communications and Water) Decree 20/1997. (X. 21.) on the declaration of the annexes of the Convention on International Civil Aviation signed in Chicago on 7th December 1944,
- Act CLXXXIV of 2005 on the technical investigation of aviation, railway and marine accidents and incidents (hereinafter referred to as Kbvt.),
- MET Decree 123/2005 (XII. 29.) on the regulations of the technical investigation of aviation accidents, incidents and irregularities;
- In absence of other related regulation of the Kbvt., the Transportation Safety Bureau of Hungary carried out the investigation in accordance with Act CXL of 2004 on the general rules of administrative authority procedure and service,
- The Kbvt. and the MET Decree 123/2005 (XII. 29.) jointly serve the compliance with the following EU acts:
 - Council Directive 94/56/EC of 21 November 1994 establishing the fundamental principles governing the investigation of civil aviation accidents and incidents, with the exception of its Annex;
 - Directive 2003/42/EC of the European Parliament and of the Council of 13 June 2003 on occurrence reporting in civil aviation, with the exception of its Annex I and Annex II.
- The competence of the Transportation Safety Bureau of Hungary is based on the Kbvt. until 31st December 2006 and on Government Decree 278/2006 (XII. 23.) from 1st January 2007 respectively.

Under the aforementioned regulations

- The Transportation Safety Bureau of Hungary shall investigate aviation accidents and serious aviation incidents.
- The Transportation Safety Bureau of Hungary may investigate aviation incidents and irregularities which - in its judgement - would have resulted in accidents in other circumstances.
- The technical investigation is independent of any administrative, infringement or criminal procedures.
- In addition to the aforementioned laws, the ICAO DOC 6920 Manual of Aircraft Accident Investigation is applicable.
- This present Final Report shall not be binding, nor shall an appeal be lodged against it.
- Persons participating in the technical investigation did not act as experts in other procedures concerning the same case and shall not do so in the future.

The IC shall safe keep the data having come to their knowledge in the course of the technical investigation. Furthermore the IC shall not be obliged to make the data – regarding which the owner of the data could have refused the disclosure of the data pursuant to the relevant act – available to other authorities.

This present Final Report has been completed based on the Draft Report which was compiled by the IC and approved by the Director-General of TSB and sent to the concerned parties and organisations – defined by law - for reflections.

ABBREVIATIONS

| AF | Air France |
|----------|--|
| ATC | Air Traffic Control |
| ATPL | Air Transport Pilot Licence |
| CVR | Cockpit Voice Recorder |
| FDR | Flight Data Recorder |
| HC | HungaroControl |
| IATA DGR | International Air Transport Association Dangerous Goods Regula- tion |
| IC | Investigating Committee |
| ICAO | International Civil Aviation Organization |
| Kbvt. | Act CLXXXIV of 2005 on the technical investigation of aviation, railway and marine accidents and incidents |
| MET | Ministry of Economy and Transport |
| MH | Malaysia Airlines |
| MSDS | Material Safety Data Sheet |
| MTCW | Ministry of Transport, Communications and Water (Közlekedési, Hírközlési és Vízügyi Minisztérium, KHVM) |
| NOTOC | Notification to Captain |
| NTA AD | National Transport Authority, Aviation Directorate (Nemzeti Közlekedési Hatóság Légiközlekedési Igazgatósága, NKH LI) |
| PSN | Proper Shipping Name |
| TSB | Transportation Safety Bureau (of Hungary) |
| ULD | Unit Load Devices |

BRIEF DESCRIPTION OF THE OCCURRENCE

| Operator |
|---------------------------------|
| Manufacturer |
| A/C type |
| A/C nationality |
| A/C registration mark |
| Location of the occurrence |
| Date and time of the occurrence |

Air Atlanta Icelandic Boeing B747-236SF Iceland TF-ATX Budapest 14 July 2007, 19:16 UTC

Notifications

The occurrence was reported to the dispatcher of the TSB at 21:08 LT on 14th of July 2007.

The dispatcher of the TSB:

- reported to TSB's head of department on duty at 21:32 on 14th of July 2007,
- notified the duty personnel of NTA AD at 21:48 on 14th of July 2007.

The Investigating Committee

On 14th July 2007 the Director-General of the TSB assigned the following Investigating Committee (hereinafter referred to as IC) for the investigation of the serious incident:

| Investigator-in-Charge | Sándor SIPOS | Accident investigator |
|------------------------|--------------|-----------------------|
| Member of the IC | Zsófia OLÁH | Accident investigator |

Zsófia OLÁH terminated her labour contract with TSB in June 2008, therefore she was replaced by László GRÉZ in the IC on 1 June 2008.

Overview of the investigation procedure

The IC determined that a piece of cargo leaked and, due to lack of cooling, strongodoured fumes were released into the cargo bay.

The IC has taken into consideration the reflections on the Draft Report received from the concerned parties when compiling the Final Report.

<u>Synopsys</u>

The aircrew noticed stinging odour in the cockpit while en route and decided to abrupt the flight. They turned back from Rumanian airspace toward Hungary and landed at Budapest Ferihegy Airport. While the overweight landing in progress, balloon pressure was lowered automatically on three wheels that subsequently got damaged during landing. The aircrew did not report emergency and did not request assistance. After landing, they told the authorities responding to the situation that it was most probably a piece of cargo that leaked some liquid with strong odour they felt. The check of the cargo area did not find traces of smoke, nor was there any indication of dangerous gases. The suspect cargo was found. There was no injury.

Time zone used in the report

Local time (LT) is used throughout the report.

1. FACTUAL INFORMATION

1.1 History of the flight

A cargo aircraft, flight No. MH6151, Manufacturer/Model Boeing-747-236SF, departed Milan-Linate (LIMC) on 14 July 2007 at 17:35 LT with a planned destination of Dubai (OMDB).

The crew felt unpleasant odour during the flight. Because the odour did not cease the captain decided to abort the flight and turned toward LHBP from Rumanian airspace. He notified the area ATC of HungaroControl at 21:16 LT while flying at FL330 of his intentions of landing at Budapest and the reason of the landing. He did not report an emergency and did not request assistance.

The airport authorities enacted the emergency action plan. The aircraft landed at 21:41 LT.

| Injuries | Crew | Passengers | Total in the a/c | Others |
|----------|------|------------|---------------------|--------|
| Fatal | | | | |
| Serious | | | | |
| Minor | | | | |
| None | 3 | 2 | 5 | |

1.2 Injuries to persons

1.3 Damage to aircraft

None.

1.4 Other damage

During the flight, about 120 kgs of material hazardous to the environment evaporated from 6 (six) barrels that were stored in the cargo bay. The IC did not receive information on other damage by the closing of the investigation.

1.5 Personnel information

1.5.1 Pilot-in-Command

| Age, gender | | 63-year-old male |
|--|-------------------|--------------------|
| Licence | | ATPL |
| Type ratings | | B-747, DC-3, DC-10 |
| | professional | 29 SEP 2007 |
| Licence validity | medical | 2 JUN 2007 |
| | ratings | n/a |
| Flying experience total, hours over 11,000 hours | | over 11,000 hours |
| Flying experience or | n the type, hours | 3,000 hours |

1.5.2 First Officer

| Age, gender | | 49-year-old male | |
|--------------------------------------|--------------|----------------------|--|
| Licence | | ATPL | |
| Type ratings B-727, B-747, L | | B-727, B-747, L-1011 | |
| | professional | 5 MAR 2008 | |
| Licence validity | medical | 31 JAN 2009 | |
| | ratings | n/a | |
| Flying experience to | otal, hours | 9,000 hours | |

1.5.3 Flight Engineer

| Age, gender | | 53-year-old male | |
|----------------------|-------------------------------|----------------------|--|
| Licence | | n/a | |
| Type ratings | | B-727, B-747, L-1011 | |
| | professional | 25 JUN 2008 | |
| Licence validity | medical | 23 NOV 2007 | |
| ratings | | n/a | |
| Flying experience to | nce total, hours 12,000 hours | | |

1.6 Aircraft information

The characteristics of the aircraft had no effect on the course of events therefore their analysis was not required.

1.7 Meteorological information

The meteorological parameters had no effect on the course of events therefore their analysis was not required.

1.8 Aids to navigation

The aircraft was equipped with navigational instruments described in the aircraft's airworthiness certificate and they functioned normally. They had no effect on the course of events therefore their analysis was not required.

1.9 Communication

The aircraft was equipped with communications instruments described in the aircraft's airworthiness certificate and they functioned normally. They had no effect on the course of events therefore their analysis was not required.

1.10 Aerodrome information

The parameters of the aerodrome had no effect on the course of events therefore their analysis was not required.

1.11 Flight recorders

The aircraft was equipped with a Cockpit Voice Recorder and a Flight Data Recorder as described in the aircraft's airworthiness certificate and they functioned normally.

1.11.1 Flight Data Recorder (FDR)

FDR data have not been evaluated because the aircraft proved to be not at fault of the incident.

1.11.2 Cockpit Voice Recorder (CVR)

The circuit breaker of the CVR was not pulled after landing, therefore whenever the external power source was connected to the aircraft, the CVR restarted. As a result, the tape did not contain information relevant to the incident flight.

1.12 Wreckage and impact information

There was no wreckage.

1.13 Medical and pathological information

The crew members of the aircraft had a valid medical certificate prior to the commencement of the flight. The IC does not have information on the crew's psychophysical condition during the flight.

1.13.1 Medical forensics examination

Not applicable.

1.14 Fire

There was no fire.

1.15 Survival aspects

There has been no life-threatening situation during the occurrence.

There was no injury.

1.16 Tests and research

There was no need to conduct tests and research for reaching the conclusion.

1.17 Organisational and management information

The characteristics of the organizational and management environment had no effect on the course of events therefore their analysis was not required.

1.18 Additional information

The IC did not receive any relevant additional information.

1.19 Useful or effective investigation techniques

The investigation did not require techniques differing from the traditional approach.

2. ANALYSIS

A cargo aircraft, flight No. MH6151, Manufacturer/Model Boeing-747-236SF, arrived from Amsterdam (AMS) to Milan-Linate (LIMC) with a final destination of Dubai (OMDB). Since there have been long delays at both airports, the crew decided to continue the route to Dubai. The aircraft received a cargo containing hazardous material in Milan. According to the description, the material that was packed in plastic barrels was Category Level 9 "hazardous to the environment".

After loading the cargo into the aircraft it departed Milan-Linate for Dubai at 17:35 LT on 14 July 2007.

The captain and the first officer felt a slight odour in the cockpit during the flight but they did not credit it much importance. Later, two passengers notified the crew that they felt a strong odour.

The captain asked the flight engineer (FE) to check the cargo bay in case they had overseen something. The FE returned a few minutes later, immediately donned his oxygen mask, and reported that a piece of cargo just under the cockpit was leaking vapour or fumes. He also told the captain he felt dizzy and was about to passing out.

It was that moment when the captain realised the first officer (FO) was acting strangely and showed the signs of hypoxia.

They looked up in the emergency manual the required procedure regarding Level Nine hazardous material (see Appendix 1). According to the document, the required procedure was to use masks with 100% oxygen. The FO and the FE donned their masks. The captain, however, was using his only occasionally because he did not feel any symptom other than the odour.

The captain then decided to land at the closest available airport.

He notified the ATC that they felt some kind of odour in the cockpit but did not report an emergency. He, however, requested a technical landing at Budapest.

The aircraft proceeded with the flight to Budapest and the captain notified the area ATC of HungaroControl at 21:16 LT while flying at FL330 of his intentions of landing at Budapest and the reason of the landing. He again did not report an emergency and did not request assistance.

The captain's priority was to land as soon as possible; he did not want release fuel or burn fuel in the waiting pattern. He opted for the overweight landing.

The IC examined the shipping documentation and determined the following:

- The shipping manifest for dangerous goods, issued by Antibioticos S.P.A., states the following: "material hazardous to environment, solid (PWS-BAL5287), hazard level 9, packaging method 911 (reference to packaging instructions). The required storage temperature as per MSDS BAL5287 (+5 C°) was missing (see Appendix 2).
- The NOTOC (which had not been signed by the cargo load inspector) also listed the dangerous goods but without packaging and handling instructions. The NOTOC listed other special goods (vaccination) that required cooling between +2...+8 C° if available (see Appendix 3), and 90 kgs of chocolate, also needing refrigeration (see Appendix 4).
- The MSDS BAL5287 document was found on board of the aircraft, in a sealed envelope. In the IATA DGR book there is no reference of the chemical listed in paragraph 2 of the document. Paragraph 7 (Handling and Storage) determines storage conditions as a well-ventilated, dry, safe area with a temperature below

+5 C° (see Appendix 5). From the above conditions the temperature condition was not met.

 The form for listing the non-radioactive dangerous goods was a 2006 edition. The answer given to question No. 37 was incorrect. The answer to question No. 51 should read "No" because the position of the package labels was incorrect (see Appendix 6). There were several packages where the UN symbol, the UN number, the PSN number, or the sender's data were covered or otherwise not clearly visible. The required storage temperature was not indicated. The ULD identification tags contained the three-letter cargo IMP code, in contradiction with the IATA DGR which requires the usage of Class/Division Numbers (see Appendix 7).

The hazardous material in the cargo bay was a synthetic raw material that is used for manufacturing pharmaceutical active ingredients. This material is solid under +5 C°. At higher temperatures it becomes a liquid, then intensively evaporates.

At Milan-Linate airport the shipment first was moved the cargo loading area, then loaded into the A2 section of the aircraft's cargo bay (see Appendix 8). The loading took several hours. Because the outside temperature was around +30 C° and the cargo bay temperature was even higher, the material was already in liquid phase during the loading. During the flight, due to lack of cooling in the cargo bay, the material evaporated and the non-airtight plastic barrels leaked out the vapours. The unpleasant odours of the vapours caused nausea. The use of the oxygen masks prevented the deterioration of the situation.

3. CONCLUSIONS

3.1 Direct causes of the occurrence

- The company that prepared the hazardous material BAL5287 for shipping (Antibioticos S.P.A.) did not indicate on the shipping documentation and on the storage containers the required temperature while in storage and during shipping, and did not provide airtight containers.
- The cargo loader while being aware of the fact that they were handling dangerous goods – did not check the MSDS upon receipt (they did not open the envelope containing the document) therefore the required storage temperature of +5 C° was neither ensured nor noted on the NOTOC.
- The required temperature of +2...+8 C° in the aircraft's cargo bay was not provided for the 149 kgs of vaccination that was listed in the NOTOC and was transported in JL position.
- The required cooling in the aircraft's cargo bay was not provided for the 90 kgs of chocolate that was listed in the NOTOC and was transported in QL position.
- Due to lack of cooling, the crystallization of the material that could have prevented evaporation of dangerous vapours could not take place.
- The cargo load inspector did not sign the NOTOC and the captain accepted it without the signature.

3.2 Indirect causes of the occurrence

• The captain was aware of the procedures of the emergency manual for Category Nine dangerous goods but he did not consider the use of oxygen mask mandatory for himself.

3.3 Risk factors that cannot be linked to the occurrence

- There were several packages where the UN sign, the UN number, the PSN number, or the sender's data were covered or otherwise not clearly visible.
- The ULD identification tags contained the three-letter cargo IMP code, in contradiction with the IATA DGR which requires the usage of Class/Division Numbers.
- There were simultaneously Air Malaysia and Air France package ID labels on the packages which is not allowed.
- The form for listing the non-radioactive dangerous goods was a 2006 edition, and the answers given to questions No. 37 and No. 51 were incorrect.
- The medical check in the captain's pilot licence expired on 2 June 2007.

4. SAFETY RECOMMENDATIONS

Similar occurrences can be prevented by complying with the relevant rules and regulations therefore there is no need to issue a specific safety recommendation.

5. APPENDICES

- 1. Aircraft Emergency Response Drills (ERG drill code)
- 2. Shipper's Declaration for Dangerous Goods
- 3. Special Load Notification to Captain (1)
- 4. Special Load Notification to Captain (2)
- 5. Material Safety Data Sheet (2 pages)
- 6. Dangerous Goods Check List for a Non-radioactive Shipment (Version 2006)
- 7. Photo
- 8. Load Sheet
- 9. Certificate of registration

Budapest, " January 2009.

Sándor SIPOS IIC László GRÉZ IC member

TSB of Hungary

WEEC and 2001/68/EC

the second

A CAR LONG MAN

1. IDENTIFICATION OF THE SUBSTANCE AND OF THE COMPANY

MATERIAL STATES

27.18.92.1

| Irade name: | BAI 5287 |
|----------------------|---|
| Other name: | PWS |
| Actual use: | Synthetical intermediate for the production of an Active Pharmaceutical ingredient (API) |
| Manufacturer (India) | DIVISTABORATORIES LTD. C |
| | Dharam Karan Road, Ameetpel, Hyderabad - 500 016, Andhra Ptadesh, India |

Contact address (Europe)

Phone number for emergencies: Antibioteos, Strada Rivotana km 6-7, 20090 Rodano (Mi), italy Tet +30-0295233324, Fax, +39-0295321134

Tel +91 40 23752921 Fax +91 40 23754252

+91 8694 272259 or +91 8694 272260, (India)

Date Revised:

+39-0295233374 (Italy) Not applicable: Original data sheet

2. COMPOSITION/INFORMATION ON INGREDIENTS

| Chemical name | CAR | Althous 21 | | |
|--|---|---|--|---|
| Moxime of | CAS reg no. | Symbol | R-phrases | Content (%) |
| 11 fen butoxycarbonyi-2 oxo (1 3)Ril | 376653.47.8 | Ar Xi N | R22. R41 | Co 92% (WW) |
| oney room J(R) yi) those of a second and | | | R51/63 | an an an an |
| | | | far an | |
| 1 left-butoxycarbonyl 2-oxo (1.3 (Ruboyr | | | | |
| blom 3(S)-yil triphenyl phosphorade | n of the Netal States of States | an an tao an Tao an tao an | | n - Star Garage (Star Star Star Star 27 - Star Star Star Star Star Star Star 28 - Star Star Star Star Star Star Star Star |

3. HAZARD IDENTIFICATION

| Most important hazards | |
|---------------------------|--|
| Ingestion: Irritation: | Hann bent swallower |
| Inhalation: | Risk of serious damage to eyes |
| Environment: | May be harmful after inhalation |
| | Toxic to aquatic organisms may cause long-term adverse effects in the aquatic environment |
| Specific hazards: | Under fire situation, this material may generate toxic gases such as COx, NO2, and poisonous and corresive fomes of HBr |

4. FIRST-AID MEASURES

Symptoms and effects

| neaning as poison | *Toxic has the same meaning as poison | | TOXIC* (= POISON) | P | HIGHLY IGNITABLE | н |
|--|--|---|---|---|--|--------|
| a the appropriate national authority may animate, cargo and the sinc-att | Dropending on the type of infectious substance, the appropriate national authority may be required to quarantine individuals, animals, cargo and the sincraft | Y | NOXIOUS | z | FLAMMABLE | П |
| ËR | OXIDISER | X | MAGNETIC | M | EXPLOSIVE | п |
| R FLAMMABLE GAS OXIDISER | IF WET GIVES OFF POISONOUS OR FLAMMABLE GAS OXIDISER | W | OTHER RISK LOW OR NONE | F | CORROSIVE | 0 |
| STIBLE OR PYROPHORIC | SPONTANEOUSLY COMBUSTIBLE OR PYROPHORIC | S | IRRITANT/TEAR PRODUCING | - | ANAESTHETIC | A |
| VIDE VIDE VIDE VIDE VIDE VIDE VIDE VIDE | NOTION S STATES | PRILI LETTER C. A | and the second se | | And a star stylendown | DRIVER |
| Call for a qualified person to meet the aircraft | All agents according to availability. No water on "Y" drill letter | Do not touch. Minimum recirculation and ventilation in affected area | Delayed infection to humans or animals | Contamination with infectious substances | Infectious substances may affect humans or animals if Inhaled, ingested or absorbed through the mucous membrane or an open wound | 11 |
| Possible abrupt loss of pressurisation | All agents according to availability | Use 100% oxygen; establish and maintain max, ventilation; no smoking; min, electrics | Smoke, fumes and heat, and as indicated by the drill letter(s) | Fire and/or explosion | Gas, flammable high fire risk if any ignition source present | 10 |
| None | All agents according to availability; no water on "\V" drill letter | Use 100% oxygen; establish and maintain maximum ventilation if "A" drill letter | As indicated by the drill letter | As indicated by the drill letter | No general inherent risk | 60 |
| Possible abrupt loss of pressurisation; minimum electrics if "F" or "H" drill letter | All agents according to availability; no water on "W" drill letter | Use 100% oxygen; establish and maintain maximum ventilation; do not touch without gloves | Eye, nose, and throat irritation; skin damage on contact | Possible corrosion damage | Corrosive, fumes disabling if inhaled or in contact with skin | 80 |
| Call for a qualified person to meet the aircraft | All agents according to availability; no water on "VV" drill letter | Do not move packages avoid contact | Exposure to radiation and personnel contamination | Contamination with spilled radioactive material | Radiation from broken/unshielded packages | 07 |
| Possible abrupt loss of pressurisation; minimum electrics if "F" or "H" drill letter | All agents according to availability; no water on "W" drill letter | Use 100% oxygen; establish and maintain maximum ventilation | Acute toxicity, effects may be delayed | Contamination with poisonous Ilquid or solid | Toxic, may be fatal if inhaled ingested or absorbed by skin | 90 |
| Possible abrupt loss of pressurisation | All agents according to availability; no water on "W" drill letter | Use 100% oxygen; establish and maintain maximum ventilation | Eye, nose, and threat irritation; skin damage on contact | Fire and/or explosion, possible corrosion damage | materials, may ignue other materials, may explode in heat of a fire | 05 |
| Possible abrupt loss of pressurisation; minimum electrics if "F" or "H" drill letter | All agents according to availability; no water on "W" drill letter | Use 100% oxygen; establish and maintain maximum ventilation | Smoke, fumes and heat, and as indicated by the drill letter(s) | Fire and/or explosion | Spontaneously combustible or pyrophoric when exposed to air | 04 |
| Possible abrupt loss of pressurisation | All agents according to availability; no water on "W" drill letter | Use 100% oxygen; establish and maintain max. ventilation; no smoking; min. electrics | Smoke, fumes and heat, and as indicated by the drill letter(s) | Fire and/or explosion | Flammable líquid or solid | 03 |
| Possible abrupt loss of pressurisation | All agents according to availability; use standard fire procedure | Use 100% oxygen; establish and maintain maximum ventilation for "A", "I" or "P" dnil letter | As indicated by the drill letter(s) | Minimal | Gas, non flammable, pressure may create hazard in fire | 02 |
| Possible abrupt loss of pressurisation | All agents according to availability; use standard fire procedure | Use '100% axygen; no smaking | As indicated by the drill letter(s) | Fire and/or explosion | Explosion may cause structural failure | 01 |
| Rev. 1 del 27/03/2007 | | BROCEDURE | | | | DRILL |
| ERG | DRILL CODE) | ONSE DRILLS (ERG DRILL CODE) | AIRCRAFT EMERGENCY RESPONS | AIRCRAFT | ALHA AIRPORT: | |
| // | | | | | | |

VEN

| | SHIPP | ER'S DECLA | | | ANGEROUS GOO | | |
|--|--|--|--|----------------------------------|--|--------------------------|------------|
| Shipper ANTIBIOTICO TR. RIVOLT | | | | Air Waybi Page ¹ | ⅢNo. 232–9207. of 1 _{Pages} | 3785 | |
| | NO (MI) ITALY | | | | | | |
| | ELLI PH.+39 02 | 2952331 | | Shipper's (optional) | Reference Number | | |
| DIVI TOWER DHARAM KA HYDERABAE NDIA - PH 4 Two complet | RATORIES LIMI IS, 7-1-77/E/1/30 IRAN ROAD AM D-500 016 ANDH 914023752921 ed and signed co the operator |)3 EERPET | ation must | WARN | | L FREIGHT FORWARD | ERS |
| TRANSPOR | DETAILS | - | | Danne | erous Goods Regulation | is may be in | breach of |
| | t is within the escribed for licable) | Airport of Departu | ire | the ap | oplicable law, subject to | legai penani | es. |
| AIRCRAFT | XXXXXX | | | | | | |
| Airport of De | estination: HYDERAE | BAD | κ. | Shipn NON- | nent type (delete pon applicab RADIOACTIVE NALDADAD | XX [| |
| NATURE AN | D QUANTITY OF | DANGEROUS GOO | DDS | | | | |
| | Dangero | ous Goods Identifica | tion | | | | |
| UN or Proper Shipping Name Class Or Divisio (Subsidia Risk) | | | | Pack- ing Group | Quantity and type of packing | Packing Inst. | Authorizat |
| UN 3077 | ENVIRONMENT HAZARDOUS SI SOLID, N.O.S. (PWS -BAL5287 | JBSTANCE, | 9 | 111 | 72 Plastic drums X 25 KGS 1Plastic drums X 5,5 KGS 2Plastic drums X 7,5 KGS 1Plastic drums X 3,5 KGS Plastic drums X 8,5 KGS 1 Plastic drums X 10,5 KGS | NET NET NET VET | |
| 24-HOUF I hereby d accurately classified, respects i internatio | eclare that the c / described abov packaged mark n proper conditional | Ation RGENCY PHONE ontents of this cons by the proper shi ed and labelled/pla on for transport acc governmental regul t requirements have | signment are full pping name, and carded, and are ording to applica lations. I declare | y and d are in all able | Name/Title of Signate F.MONTOLI EXPORT Place and Date | MANAGER | |

[

| | į |
|---|--------|
| | |
| | Ĩ |
| ¥ | ARPORT |

•7


SPECIAL LOAD - NOTIFICATION TO CAP FAIN



 $\left(\right)$ NOTOC Rev. 1 del 26/01/05

| \bigcap | | Г | <u> </u> | | T | - | | | | , , |
|-------------------------|--|------------------|--|--|---------------------|---------------------------|---|---|--|---|
| /05 | | | Position | A2 | | Position | 75 | | | d |
| Rev. 1 del 26/01/05 | Prepared by: (Name & sign) MXPFEAZ PARADISO GIORGIO | | ULD Identification | PMC-60006MH PMC-60006MH PMC-60006MH PMC-60006MH PMC-60006MH PMC-60006MH | I O A D F D | ULD Identification | PMC-00691MH | AFT | | PEP Foods & Vegetablos PER Perishable PES Fish & Seafood RSB Polimeric Boads SWP Sporting Human Life SWL Valuable Cargo |
| 34 | repared by: MXPFEAZ I | | ERG (Drill) Code | 22222 | | IMP Code | PER | CONTAINING DANGEROUS GOODS HAVE BEEN LOADED ON THE AIRCRAFT | | MP CODE: Living Human Organ Muntitons of war Muntitons of war Muntitons of war arrises mate from or an arrise of species steed in CITES Flowers |
| SI-Som A | 74FCC | | CAO (X) | | | | SIBLE | DED ON 1 | | P CODE: Living Human Organ Magnetized Material Munitions of war Larving Traylows, short on arread mate from or conten- parts of species Mater in Cl Flowers Meat |
| | 741 | | IMP Code | RMD RMD RMD RMD RMD RMD | | ц. | IF POS | EN LOA | | |
| N | Aircraft registration: | | Packing Group | | | Informatic | I +2/+8 C° | HAVE BEB | | 07 |
| ALIA | | | Radioactive Material Category | | | Supplementary Information | ETWEEN | GOODS | rnation: | OTHER SPECIAL AVI Livo Animals EAT Foodstuffs FIL Undeveloped Films FIR Frozon Goods HER Frozon Goods HER Human Remains ICE Dry Ice |
| 10 (1 | 14/07/07 | Net Otantity or | Transport Index per package | 25 KG 5,5 KG 7,5 KG 3,5 KG 8,5 KG 10,5 KG | | IdnS | PLS. KEEP COOL BETWEEN +2/+8 C° IF POSSIBLE | NGEROUS | Other Information: | |
| | Date: | : | Packing Instruction Number | 116 116 116 116 | | | PLS. KEE | INING DAI | | C Combustible B (CAO) C (CAO) D (CAO) D (CAO) B (CAO) G (CAO) S (CAO) |
| NUTIFICATION TO CAFTAIN | 6151 | | Number of Packages | 2 - | | Quantity | 149 KG | ES CONTA | | Spontaneously Combustle Explosive 1.4B (CAO) Explosive 1.4C (CAO) Explosive 1.4C (CAO) Explosive 1.4D (CAO) Explosive 1.4S (CAO) Explosive 1.4S (CAO) |
| | HM | | Class or Div. for Class 1-Comp. Group (Sub.Risk) | <u>~~~</u> ~~~ | | Number of Packages | 10 | G PACKAG | Cet 1 | N N N N N N N N N N N N N N N N N N N |
| SPECIAL LUAU - | 5 Flight Number: | | Proper Shipping Name (including Technical Name, if any) | ENVIRONMENTALLY HAZARDOUS SUBSTANCE, SOLID,N.O.S. | | cription | | T 10 CONSTRUCT THAT ANY DAMAGED OR LEAKING PACKAGES | Captain's Signature: | ROX Oxidizor RPB Toxic substance RPG Toxic Gas (CAO) RRW Radioactive cat! whito RRY Radioactive cat. II yellow RRY Radioactive cat. II yellow RRY Radioactive cat. Fissile |
| <i>Emalaysia</i> S | Malaysia Airlines | | Proper Shi (including Techn | ENVIRONMENTALLY H. SOLID,N.O.S. | | Contents and Description | ES | | ing Supervisor): C | whon Wet us Whon Wet e 13G (CAO) s Substanco neevon neevon artier: Ramp. |
| É Ma | Carrier: | | UN or ID Number | UN3077 | l ä | | VACCINES | | HERE IS N ned by Load | |
| АLНА АІВРОНТ! | Station of loading: MXP Carrier: | DANGEROUS GOODS: | Air Waybill | 232-92073785 | OTHER SPECIAL LOAD: | Air Wavbill | 23 | | Aircraft Loaded by (to be signed by Loading Supervisor): | DANGEROUS GOODS IMP CODE RCL Cryogonic Liquid REW Dangero RCM Corrosive RCM Revision RCM Corrosive RCM Infoctiou RCM Corrosive RCM Revision RCM Franmablo Gus RMD Miscella RFL Flammablo Gus RMD Miscella RFL Flammablo Gus ROP Organic RFS Flammablo Solid ROP Organic RFS Flammablo Solid ROP Organic Distribution : Captain: Handler: MXP Co |
| H H | Station | DANG | Station of Unloading | Т М | OTHE | Station of | KUL | | Aircraf | |

Nº3



Eye contact

-Ja adinati

Ingestion:

inhalation:

Plush skin with plenty of sosp and water for at least 16 mester while removing continumated clothing and shoes. Get next as and it initiation develops or pensists.

Flush eyes with plenty of water for at least 15 minutes accasionady lifting the upper and lower eyesds. Get medical an

If vectories conscious and alert, give 2-4 cupfuls of neik of water Never give anything termouth teran unconscious person. Get

Hermove from exposure to fresh air manerhately of not breatting (yes arribbal respiration, if theathing is difficult, give oxygen, Get mouts to mouth respiration.

5. FIRE-FIGHTING MEASURES

| Suitable extinguishing media. Not suitable extinguishing media. | Finam-carbon dioxide ((,/) + water spray Not known |
|---|---|
| Special protective equipment for firefighters | in the event of the wear a cell contained becalling apparatus and a bindedbye suit. |
| Exposure hazards (combustion products). Special methods (on small fires) | Under fire situation, this material may deherate forc gases such as COX, NO2, and poisonous and correspective times of HBr " alreads heaving disposed to the and if conditions period, let fire them taelf and since water may increase the area contaminated Cove containers harks such spray water. |

6. ACCIDENTAL RELEASE MEASURES

| Personal precautions | When additionable personal sected we adoptment (refer to section, 6) during creating. Avoid contact with eyes and skin, Avoid critication, Step ockerst |
|----------------------------|---|
| Environmental precautions: | Drugsed financents is enabled material or samplery server system of recommended could of a watering enter drams of watercourses contact user Units and and Spenny |
| Methods for cleaning up | Service she are invested about out of Sweep op, place in a solid many participant for other disprisal. Residual trace can be wiced |


T. HANDLING AND STORAGE


| Handling: | and the second |
|----------------------------|--|
| Technical | Plandle with appropriate personal protective equipment deter to |
| measures/Precautions | Sochon 8, sinder ventilation. Azoid contact with eyes and skin |
| Safe handling: | Keep away from theat and sources of grittion. Weat personal |
| Storage: | protective equipment. |
| Technical measures/Storage | Keep containers tightly closed in a dry and well-ventilated place |
| conditions | at 5 °C. Store in a place accessible by authorized persons only |
| incompatible products: | incompatible with strong acids and bases. |


| RF0/384/5/2007 NEST-BRK | Emalaysia | | 48 Orientation labels Tes No NIA 49 For Magnetized Material, | the Handling label 50 "Cryogenic Liquid" label 51 All labels correctly affixed and have all irrelevant marks and labels been removed | For overpacks: 52 If specification markings are not visible, the required statement marker | 53 Packaging Use markings as required must be clearly visible or reproduced on the outside of the overnack | 54 If more than one overpack. | 55 Cargo Aircraft Only restrictions | | Verifield As. | | | @splkimp/Jan2003 | | N | ≌6 |
|-------------------------|---|---|---|---|---|---|--|---|---|--|--|--|--|---|---|---|
| 384 | 3 | | | | | Vans | | T | | X Y | 6 ¥ | ۲ vo | | 8 | र र्ज | 7 1 |
| 6 | - | | vN NΩ | | | עטאַג | (,⊊vr) ⊓ | 12 | | XX X | | | ממ הר | П | | X, D |
| Æ | | | تو هر | 2 2 | | | | | ۶ă M | | | | | M | | 2 |
| on 2006) | Se the shipment DRILL CODE(S) | Signature: | ARWAYBILL Ye 34 The handling information box [shows the applicable statement | CKS | delitivered as shown on DGD MARKINGS 37 For UN snertification Parkaring | | .c | tious substance package Proper Shipping Name(s) Jing technical name where | | The Net Quantity of Explosives And the Gross weight of the Package | the Name and Leichnone number of a person responsible for Division 6.2 shipment 42 If applicable, the special | c | Uption in the parkage 44 For Limited Quantities: "Ltd Qty" or "Limited Quantities" | LABELLING 45 The Primary Risk label(s) with Class or Division | els umber | 47 Cargo Aircraft Only label on the same surface near the Hazard label(s) |
| SHIPME | L No retu | FLAVE | ¥⊠. | 8 19 DX | 20 | XXX | N | শ্ব | | Ø | M D | <u>a</u> a | ĭ | a a | ě | র্ |
| IVE | T X | 40 | Yes No | | MATIO | | בו סנ | | | K)O | | | ، چ∑ | | ۱ [| |
| RADIOACI | DEST: | W/hse check Full name: | | on A1, A2, A51 applicable 3overmental attached or Class 1 if | IDLING INFOR | Emergency Contact Number for South-Africa or via South Africa United Arab Emirates | For Self-Reactive and related substance of Class 4,1 and Ormanic nervides of Class 5,2 | The mandatory statement shown Prior arrangement statement | wn of signatory indicated | ipper alteration(s) ne signature | s. TERRITORY J.S.A; DGD present | y Contact USG-12 pproval | obtained as per USG-07, permit number mentioned on DGD and piece(s) marked accordingly | pproval r USG-03 plosives, led and | USG-05 USG-05 the EX number | he DGU |
| JR A NON-F | -92 073785- | .Or | AUTHORIZATIONS 17 If "T packing instruction used the word "Limited Quantity | Special provision A1, A2, A51 A81 or A109 if applicable Indication that Governmental authorization is attached 20 Requirements for Class 1 if | ADDITIONAL HANDLING INFORMATION 21 State and Operator variations X | 22 Emirgency contact Number for. South-Africa or via South Africa [United Arab Emirates | 23 For Self-Reactive and related substance of Class 4,1 and Omanic nerwides of Class 5 | The mandatory statement sho 24 Prior arrangement statement for Class 6.2 infectious | substance shown 25 Name and Title of signatory place and Date indicated | 26 Signature of shipper 27 Amendment or alteration(s) signed with same signature | U.S.A. OR VIA U.S. TERRITORY ONLY 28 For transit via U.S.A; C | 29 The Emergency Contact Number as per USG-12 30 For UN 1057; approval | obtained as per USG-U/ permit number mentione and piece(s) marked acc | 31 For UN 3355;approval obtained as per USG-03 32 For Class 1, Explosives, approval obtained and | EX number mentioned on Piece(s) as per USG-05 33 For UN 3268 is the EX number | mentioned on the DGD |
| STFC | 2 - 9 | | 1 | | | | | | | | | | | | | |
| X LI | AWB: 232 | Signature: | NIA | Ø | | | | | DØ, | | Ìک | | য়য়) | 9ed | 2 | |
| HEO | AW | - | ₽⊡ | | | L Ye | | | | | | | | | D ک | |
| | Trefuse a shipment before all items have been checked. If any question is answered with "NO' refuse the shipment TOL OT AWB: 232 -92 073785 DEST: HYD DRILL CODE | Di Aschiavoni Sri Di Attorio n° 8/10 | L 1 STCA +E (MI) - arue 1VA 04664590157 SHIPPERS DECLARATION Yes 1 Two copies in English 2 Full name and address of | F | or Departure: Desunation is not shown enter it. The number of pages shown The non-applicable Aircraft Type [and the unor "Bodicachius" | 2 | ses | Class of Division, and the Class 1 the Compatibility group UN or ID number, preceded by | ng group . diary Risk | S. | (net or Gross, as applicable) per package 14 If different Dangerous Goods are [moded in one outer newhoring | - Containing Class 6.2 | - All packed in one - "Q" value 15 Overpack: | - Indication "Overpack used" | NS | |
| ×. | | | SHIP SHIP | | 002 | | | ງບລະ 0 0 | . 5 | 13 0 U | 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 | 2800 | 1504 | -92 e | PAC 16 P | |

6









| | I No: | | | | ue (C | |
|--|---|--|---|------------|---|--------------------------|
| MOIT | 3. Aircraft Serial No. 23711 | bùa | | | in the Civil Airc | |
| ICELANDIC CIVIL AVIATION ADMINISTRATION CERTIFICATE OF REGISTRATION | 2. Manufacturer and Model of Aincraft Boeing 747-2355F | Bullfinch Limited Clarendon House, 2 Church Street, Hamilton HM1, Burnuda | Flugfélagið Atlanta hf (Air Atlanta Icelandic) id. 650387-1938 Hlíðasmára 3 201 Kópavogur Ísland | | 9.It is hereby certified that the above described aircraft has been duly entered on the Civil Aircraft Register of Iceland in accordance with the Convention on International Civil Averton 67 December 1944, and according to current Icelandic Law and Heyutations. | 05 Signature |
| No. 842 ICE | 1. Registration: TF-ATX | 4. Owner Bullfin 5. Address Claren | 6. Holder Flugfél 7. Address Mlíðasi | 8. Remarks | It is hereby certified th egister of Iceland in ac ecember 1944, and ac | Date of issue: 17.8.2005 |