

LOKAÐ MEÐ BÓKUN


Case no.: **22-110F022**

Date: **22. December 2022**

Location: **Enroute to Ísafjörður (BIIS) from Akureyri (BIAR)**


Description: **Right nacelle fuel filter drain failure**

Aircraft TF-MYB (Textron B200GT) was close to the Westfjords in Iceland, enroute to Ísafjörður (BIIS) from Akureyri (BIAR), when the right engine shut down, due to loss of all fuel from the right-wing tanks during the flight.



The aircraft returned to BIAR with one engine operative.

Figure 1: Flight path



After landing it was discovered that the right nacelle firewall fuel filter drain, on the lower side of the cowling forward of the firewall, had failed and was missing its core part. As a result, the right-wing fuel tank drained completely, and the right engine shut down due to fuel starvation (Figure 2-4).

Figure 2: Failed drain valve located just forward of the firewall on lower side nacelle cowling



Figure 3: Right nacelle firewall fuel filter drain

The left nacelle firewall fuel filter drain was also inspected after the serious incident. The inspection revealed that the core part of the fuel filter drain had partially migrated out and was likely very close to failure. If the migration would have continued to such failure, that would also have caused loss of fuel in the left wing with fuel starvation of the left engine. See Figure 4.





Figure 4: Left nacelle firewall fuel filter drain

After the incident, the partially failed left nacelle firewall fuel filter drain was removed and the left-wing fuel tanks were drained. When draining the fuel from the left-wing fuel tanks, some water was discovered in the fuel.

According to the Beechcraft Super King Air Models B200GT & B200CGT Pilot Checklist for aircraft TF-MYB, the fuel filter drain should have been drained prior to the first flight of the day (Figure 5 and Figure 6).



PILOT CHECKLIST—MODEL B200GT/B200CGT

PROCEDURES BY FLIGHT PHASE

PREFLIGHT INSPECTION

NOTE

After the first flight of each day, the Preflight Inspection may be omitted except for items marked with a "+". (Fuel tank Caps and Engine Oil Quantity/Filler Cap need not be checked unless system(s) were serviced.) External inspections with flaps down may be conducted at intervals deemed appropriate by the pilot.

Cabin/Cockpit

1. Monogram Electric Toilet (if installed)KNIFE VALVE OPEN
- + 2. BaggageSECURE
3. Emergency ExitSECURE AND UNLOCKED
4. Control LocksREMOVE AND STOWED
5. Trim TabsSET TO "0" UNITS
6. Condition LeversFUEL CUTOFF
7. Landing Gear ControlDN
8. Parking BrakeSET
9. Ignition and Engine StartENSURE OFF
10. Left PFD, MFD, Right PFDCLEAN
(See Section 8 of the POH/AFM for instructions)
11. BatteryON, CHECK 23 VOLTS MINIMUM
12. Stall Warning HeatON
13. Left and Right Pitot HeatON, THEN OFF
L-R Pitot Heat CAS MESSAGE REMOVED, THEN DISPLAYED
14. Fuel Quantity (main and auxiliary)CHECK
15. Gear Down AnnunciatorsILLUMINATED
16. Flap Control (if desired)APPROACH, THEN DOWN
(check indicator)
17. Airstair Door (250) Circuitry (N-20)CHECK
18. Airstair and Cargo Door (250C) Circuitry (N-20)CHECK
19. Oxygen System Preflight Inspection (N-21)COMPLETE
20. Stall Warning HeatOFF
- +21. BatteryOFF

Left Wing and Nacelle

1. Cabin Door Seal, Step Extension Cable, Light Wire, Damper, and HandrailsCHECK
2. Cabin WindowsCHECK
- + 3. Auxiliary Fuel Tank CapSECURE

Continued on Next Page

JULY 2018 N-2 P/N 434-590168-0005

Figure 5: Beechcraft Pilot Checklist – Preflight inspection

The Fuel Filter on the left nacelle is to be drained per item 24 on page N-3, prior to the first flight of the day. See Figure 6.

The Fuel Filter on the right nacelle is to be drained per item 18 on page N-5, prior to the first flight of the day. See Figure 6.

PREFLIGHT INSPECTION (Cont)

4. Flaps (condition, asymmetry protection and flap tracks).....CHECK
 5. Oil Breather VentCLEAR
 + 6. Brake Lines, Brake Wear, Brake Deice Lines (if installed).....CHECK
 7. Fire Extinguisher (if installed).....CHECK PRESSURE

FIRE EXTINGUISHER PRESSURE VS. TEMPERATURE

°F	-40	-20	0	20	40	60	80	100	120
	-40	-29	-18	-7	4	16	27	38	49
PSI	190	220	250	290	340	390	455	525	605
Range	to	to	to	to	to	to	to	to	to
	240	275	315	365	420	480	550	635	730

8. Aileron and Tab.....CHECK
 9. Flush Outboard Wing Fuel Tank SumpDRAIN
 10. Static Wicks (5)CHECK
 11. Navigation, Recognition, & Strobe Lights.....CHECK
 +12. Main Fuel Tank CapSECURE
 13. Stall Warning VaneCHECK AND VERIFY WARM
 +14. Tiedown.....REMOVE
 15. Outboard Deice Boot and Stall StripCHECK
 16. Ice Light.....CHECK
 17. Heated Fuel VentCLEAR
 18. Ram Scoop Fuel Vent.....CLEAR
 19. Gravity Line DrainDRAIN
 20. Inverter Cooling Louvers.....CLEAR
 21. Wing Leading Edge Tank Sump.....DRAIN
 +22. Landing Gear (doors, wheel well, strut, tires, brakes).....CHECK
 +23. ChockREMOVE
 +24. Fuel Filter and Fuel Strainer Drains.....DRAIN
 +25. Engine OilCHECK QUANTITY, CAP SECURE
 26. Engine Compartment Door (outbd).....SECURE
 27. Exhaust Stack (outbd).....CHECK FOR CRACKS
 28. Top Cowling Locks (outbd).....SECURE
 29. Nacelle Cooling Ram Air InletsCLEAR
 +30. PropCHECK PROP AND DEICE BOOT CONDITION
 31. Engine Intake.....CLEAR
 32. Top Cowling Locks (inbd).....SECURE
 33. Exhaust Stack (inbd).....CHECK FOR CRACKS
 34. Generator Cooling Inlet.....CLEAR
 35. Engine Compartment Door (inbd).....SECURE,
 BLEED VALVE EXHAUST CLEAR

Continued on Next Page

PN 434-590168-0005

N-3

JULY 2018

PREFLIGHT INSPECTION (Cont)

17. Engine Compartment Door (outbd).....SECURE,
 BLEED VALVE EXHAUST CLEAR
 18. Fuel Filter and Fuel Strainer Drains.....DRAIN
 +19. Landing Gear (doors, strut, tires, wheel well).....CHECK
 20. Fire Extinguisher (if installed).....CHECK PRESSURE
 +21. ChockREMOVE
 22. Heated Fuel VentCLEAR
 23. Ram Scoop Fuel Vent.....CLEAR
 24. Gravity Line DrainDRAIN
 25. Inverter Cooling Louvers.....CLEAR
 26. Wing Leading Edge Tank Sump.....DRAIN
 +27. External Power Door.....CLOSED
 28. Ice Light.....CHECK
 29. Outboard Deice Boot and Stall StripCHECK
 +30. Tiedown.....REMOVE
 31. Flush Outboard Wing Fuel Tank SumpDRAIN
 +32. Main Fuel Tank CapSECURE
 33. Navigation, Recognition, and Strobe Lights.....CHECK
 34. Static Wicks (5)CHECK
 35. Aileron and Bendable TabCHECK
 36. Flaps (condition, asymmetry protection, flap tracks,
 limit switches, and position transmitter).....CHECK
 +37. Brake Lines, Brake Wear, Brake Deice Lines (if installed).....CHECK
 38. Oil Breather VentCLEAR
 +39. Auxiliary Fuel Tank Cap.....SECURE
 40. Cabin WindowsCHECK

Right Aft Fuselage

1. Lower AntennasCHECK
 2. Ventral Fin Drain Holes.....CLEAR
 3. Lower Aft Cabin Access Door.....SECURE
 + 4. Tiedown.....REMOVE
 5. Oxygen Service Access Door.....SECURE
 6. Static PortsCLEAR
 7. Cabin Air Exhaust.....CLEAR
 8. Access Panel.....SECURE

Continued on Next Page

PN 434-590168-0005

N-5

JULY 2015

Figure 6: Drain the Fuel Filter both on the left nacelle and on the right nacelle

The investigation revealed that normally the flight operator only drained these two drains during a maintenance inspection every two weeks, instead of daily as required per the Pilot checklist.

This was only the case for the two Firewall Fuel Filter Drains, but other drains were being drained daily as required.

According to the flight operator, the reason for not following the Pilot checklist and perform this drain before the first flight every day was the following:

- 1) These drains were hard to reach for the flight crew.
- 2) The type of the drain was such, different from other drains on the aircraft, that it required a different tool that was not available onboard the aircraft.
- 3) The flight operator considered draining this type of a drain a maintenance task, rather than a flight crew task.

- 4) The flight operator decided to have these two drains, drained during maintenance checks instead of by the pilots during the daily checks.
- 5) The aircraft was often operated at airports where mechanics were not available, therefore it was hard to schedule it as a maintenance task during daily inspection and was moved to a maintenance inspection performed at a two-week interval.

SIA-Iceland believes that water accumulated in the fuel system, at its lowest point at the Firewall Fuel Filter Drain, as the flight operator was only draining these two drains at two-week intervals instead of during daily preflight inspection.

This allowed accumulated water at the fuel filter drain to freeze, slowly migrating out the core part of the Firewall Fuel Filter Drain.

As a result, the core part of the Firewall Fuel Filter Drain on the right nacelle migrated completely out, allowing the fuel in the right wing to drain out of the aircraft during the serious incident flight (Figure 3).

This also allowed the core part of the Firewall Fuel Filter Drain on the left nacelle to partially migrate out (Figure 4).

Since the serious incident, the flight operator has changed its procedures, draining the Firewall Fuel Filter Drains daily.

SIA-Iceland informed NTSB of the case and requested that the manufacturer (Textron Beechcraft) would be notified of this incident and asked to evaluate if a "Communique" or a Service Letter to flight operators was needed. The NTSB notified the FAA, the aircraft manufacturer (Textron) and the engine manufacturer (Pratt & Whitney) as a result of this request.

SIA-Iceland closed this case with a booking on 23. Nóvember 2023.